


SPARE PARTS LIST
BMR 3300 4400 5500 6600

FINAL ASSEMBLY

OCT 2018 to present



SPARE PARTS LIST
BMR 3300 4400 5500 6600

Pos	CPN	Qty	Description
1	288790-01G-800	1	EXT PL WLDMT, BMR, WELD-ON,ST,G
1	288790-101-800	1	EXT PLT WLDMT, BMR, WELD-ON, SST
1	288790-111-800	1	EXT PLT WLDMT, BMRW, WELD-ON, SST
1	288790-11G-800	1	EXT PLT WLDMT, BMRW, WELD-ON, ST, G
1	288790-121	1	EXT PLT WLDMT,BMR,BOLT-ON,SST
1	288790-131	1	EXT PLT WLDMT,BMRW,BOLT-ON,SST
1	288790-21	1	EXT PLT WLDMT,BMR,BOLT-ON,ST
1	288790-21-500	1	EXT PLT WLDMT, BMR, BOLT-ON, ST, PRIMER
1	288790-31	1	EXT PLT WLDMT,BMRW,BOLT-ON,ST
1	288790-31-500	1	EXT PLT WLDMT, BMRW, BOLT-ON, ST, PRIMER
2	286290-01	2	UNIT MOUNTING PLATE WELDMENT, STEEL
2	286290-11	2	UNIT MOUNTING PLATE WELDMENT, STAINLESS STEEL
2	286290-21	2	UNIT MOUNTING PLATE WELDMENT, STEEL, PRIMER
3	901615-03	2	HEX FLANGE BOLT, 5/8"-11 X 1-3/4" LG.
4	902013-15	2	FLAT WASHER, 5/8"
5	901023-04	2	FLANGE LOCK NUT, 5/8"-11
6	903159-01	2	NYLON STOP NUT, 1"-8
7	905381-01	2	HEX CAP SCREW, FULL THREAD, 5/8"-11 X 4" LG.
8	286295-01	2	GUSSET